

The Barrton Manager

From: The Barrton Manager
Sent: Monday, October 7, 2024 2:26 PM
To: The Barrton Manager
Cc: barrtontaskforce@yahoo.com
Subject: Barrton Restoration Project Update - C Stack, Drop 12b
Attachments: Swing Stage Drop Layout 100124.pdf

Follow Up Flag: Follow up
Flag Status: Flagged

Hello Fellow Owner,

The Structural Integrity Project has progressed to your area of the building. Specifically:

- **C Stack, Drop 12b - east facing without balcony**

A layout of owner units and the associated Project swing stage “drops” is attached for your reference.

All windows and sliding glass doors (SGDs) will be covered in plastic for the duration of the work in these areas. Various noises such as tapping (testing to determine stucco delamination), grinding and drilling will occur for prolonged periods. Please keep all non-covered windows and SGDs of your unit **closed** to minimize dust in your apartment.

Note that the duration and extent of work in these areas can only be determined as work progresses on the individual drop.

Additional Project information is posted in the Barrton lobby. Please refrain from questioning Sheri or the CPS team, rather refer any questions and/or concerns to the Structural Integrity Task Force (email: BarrtonTaskForce@yahoo.com).

Thank you for your continued patience and support through this necessary process.

The Structural Integrity Task Force

**This email has been sent blind copy to all C Stack owners, posted on site, and posted on the Barrton website.*

Sheri Barsoum, LCAM
Association Manager
The Barrton Apartments

The Barrton Condominium
Swing-stage & scaffolding layout

